

September 25, 2009

Ms. Velma Rogers Business Manager KBR Government and Infrastructure Kellogg, Brown & Root, Inc. 5050 Wright Road, Bldg. C Houston, Texas 77032

Subject: ERC Project No. 0907202 Limited Asbestos Survey Building A 9910 Kash Road Stafford, Texas

Dear Ms. Rogers:

As per your request, ERC Environmental Consultants Inc., has performed a Limited Asbestos Survey at Building A, 9910 Kash Road located in Stafford, Texas. The results of the investigation, performed on **September 1st and 2nd, 2009,** can be found in the enclosed report.

Asbestos *was* detected above the regulatory level of 1% in some of the samples collected at the subject property.

Please feel free to contact us at your earliest convenience should you have any questions or concerns.

Respectfully submitted,

Km Az-P

Kommy M. Azarpour, P.E. Principal - ERC



BUILDING MATERIAL SURVEY For Asbestos Containing Building Materials

Building A 9910 Kash Road Stafford, Texas

ERC PROJECT NO. 0907202

PREPARED FOR:

Kellogg, Brown & Root, Inc. 5050 Wright Road, Bldg. C Houston, Texas 77032

PREPARED BY:

ERC Environmental Consultants Inc. 10801 Hammerly Boulevard, Suite 100 Houston, Texas 77043

Tel: (713) 290-9444 Fax: (713) 290-9441

September 2009

Page No.

SECTION I – PROJECT DIRECTORY

SECTION II – EXECUTIVE SUMMARY

1.0	Introduction	1
2.0	Findings	1

SECTION III – REPORT FOR ACBM

1.0	Building Description	2
2.0	Building Material Survey For ACM 2.1 Survey Method 2.2 Limitations	2
3.0	ACBM Homogeneous Material Listing	3
4.0	Asbestos Sample Results Summary	4
5.0	Conclusions and Recommendations	6

APPENDICES

A,	Detailed	Asbestos	Analy	/tical	Results
<i>،</i> ۱	Dotanou	10000100	7 11 101 9	, uou	1.0004110

- B) DrawingsC) PhotographsD) Certificates

SECTION I

CONTACT:

Ms. Velma Rogers Business Manager

MAILING ADDRESS:

5050 Wright Road, Bldg. C Houston, Texas 77032

PROJECT:

0907202 Building A 9910 Kash Road Stafford, Texas

CONSULTANT:

ERC ENVIRONMENTAL CONSULTANTS INC.

Contact:

Ronnie J. Morgan Project Manger DSHS License # 20-5644

Kommy M. Azarpour, P.E. Principal DSHS License # 10-5238

K m A 3-A.

 Address:
 10801 Hammerly Boulevard, Suite 100 Houston, Texas 77043 Tel: (713) 290-9444 Fax: (713) 290-9441 www.erc-tx.com

SECTION II

1.0 INTRODUCTION

On September 1st and 2nd, 2009, ERC representatives conducted a Limited Building Material Survey for the presence of Asbestos-Containing Building Materials (ACBM) at *Building A* located at *9910 Kash Rd.* in *Stafford, Texas.*

A total of **thirty-five (35)** bulk samples of suspect asbestos materials were collected, in the concerned areas within the subject property and submitted for analysis for asbestos content. Any materials found to contain greater than one percent (>1%) asbestos by weight are considered to be Asbestos Containing Building Materials (ACBM). This survey considered all accessible areas of the building. However, no destructive procedures were employed during the survey (i.e. no column or ceiling penetrations were made to view the ceiling pan or pipe chases). Therefore, any materials that have not been specifically evaluated by bulk sampling in this survey must be tested prior to disturbance of these materials.

2.0 FINDINGS

Eleven (11) of the **thirty-five (35)** samples collected (generally a minimum of three (3) samples per material was collected), tested positive for asbestos content of greater than one percent (>1%).

These materials tested **positive** for asbestos content.

- Sheetrock (white) with texture (white) and joint compound (white)

These materials tested *negative* for asbestos content.

- Cork board (brown) and mastic (brown) and ceiling tile (white)
- Cove base (black) and mastic (tan)
- 12"x12" Floor tile (beige with white pattern) and mastic (yellow)
- Roof flashing (black)
- Roof core (black) and insulation (brown)
- Roof Mastic (black)

SECTION III

1.0 BUILDING DESCRIPTION

The subject property Building A is located at 9910 Kash Rd. in Stafford, Texas. The property consists of a single-story office building that is approximately 13, 550 sq. ft. The exterior walls are brick with a concrete foundation. The roof is built-up and covered with rocks and tar. Interior flooring consists of carpet, floor tile, and sheet flooring. The ceiling is a mixture of suspended and sheetrock. Walls are sheetrock throughout the facility. Above the suspended ceiling is rollout fiberglass insulation and a bare metal deck.

2.0 BUILDING MATERIAL SURVEY FOR ACM

2.1 Survey Method

Representative bulk material samples were collected from the suspect asbestos-containing surfacing materials, and miscellaneous materials from each of the assigned homogeneous areas. All samples were collected at random locations throughout the subject project. Samples were placed in seal-able heavy-duty plastic bags and numbered to identify the samples. The samples were then submitted to a certified laboratory for analysis of asbestos content by Polarized Light Microscopy (**PLM**).

2.2 Limitations

Our survey was limited in scope to the extent involving, the following:

- This survey identified only easily accessible asbestos-containing building materials within the subject property and ERC's scope of work;
- This survey was non-destructive in nature and bulk samples were collected in discrete locations when possible;
- Surfacing, Thermal Insulation and Miscellaneous materials were required to be sampled in bulk form for ACBM; and
- > No materials were presumed to be asbestos-containing materials.

Every attempt was made to identify and sample suspect ACBM with ERC's scope of services. It is possible that inaccessible or unidentified materials may be exposed during the proposed renovation or abatement activities. Such materials should then be sampled and evaluated at that point of time. Our Conclusions and Recommendations are made based on our observations and results of the laboratory analysis performed. This report is prepared for the sole benefit of **Kellogg, Brown, & Root, Inc.** and may not be relied upon by any other person or entity without the written authorization of ERC.

3.0 ACBM HOMOGENEOUS MATERIAL LISTING

Homogeneous Areas (HA) are defined as surfacing material (S), thermal system insulation (TSI) and miscellaneous materials (M) that are uniform in texture, color and appear identical in every other respect. It is recommended by EPA and TDSHS that at minimum, three (3) random bulk material samples be collected from each material area. Each homogeneous material was categorized as friable or non-friable. The "Identified Homogeneous Areas" table lists the homogeneous areas identified at *Building A* located at *9910 Kash Rd.* in *Stafford, Texas.*

I General Location	Friability
e Throughout building	NF
e) North Building Office 112	F
e Throughout building	NF
ic Throughout building	NF
Closets near Reception Area	NF
South roof	NF
tion South roof	NF
Air duct penetration South roof	NF
tion North roof	NF
North roof	NF
	North roof

Identified Homogeneous Areas

Legend

M Miscellaneous

S Surfacing

F NF

Friable Non-Friable

TSI Thermal System Insulation

Positive for Asbestos

4.0 ASBESTOS SAMPLE RESULTS SUMMARY

A total of *thirty-five (35)* bulk samples of suspect asbestos materials were collected, in the concerned areas within the subject property and submitted for analysis for asbestos content by PLM. Any materials found to contain greater than one percent (>1%) asbestos by weight are considered to be Asbestos Containing Building Materials (ACBM). General sample location, sample type and results are presented in the following table. Detailed laboratory results are presented in **Appendix A**.

SAMPLE NO.	LOCATION / DESCRIPTION	PERCENT ASBESTOS	F/NF
*A-01	Sheetrock (white) with texture (white) and joint compound (white) / Main entrance by Admissions office	2%C-TX 2%C-JC	NF
*A-02	Sheetrock (white) with texture (white) and joint compound (white) / Men's Restroom outside Admissions office	2%C-TX 2%C-JC	NF
*A-03	Sheetrock (white) with texture (white) and joint compound (white) / Office A104 in corner	2%C-TX 2%C-JC	NF
*A-04	Sheetrock (white) with texture (white) and joint compound (white) / Hallway across from Office A107	2%C-TX 2%C-JC	NF
*A-05	Sheetrock (white) with texture (white) and joint compound (white) / Office A112 in corner by window	2%C-TX 2%C-JC	NF
A-06	Cork board (brown) and mastic (brown) and ceiling tile (white) / Wall of Office A112	ND	F
A-07	Cork board (brown) and mastic (brown) and ceiling tile (white) / Wall of Office A112	ND	F
A-08	Cork board (brown) and mastic (brown) and ceiling tile (white) / Wall of Office A112	ND	F
*A-09	Sheetrock (white) with texture (white) and joint compound (white) / Janitor closet near Office A114	2%C-TX 2%C-JC	NF
*A-10	Sheetrock (white) with texture (white) and joint compound (white) / Office A114 in corner	<1%C-TX 2%C-JC	NF
*A-11	Sheetrock (white) with texture (white) / Office A117 in corner by	2%C-TX	NF

SAMPLE NO.	LOCATION / DESCRIPTION	PERCENT ASBESTOS	F/NF
A-12	Sheetrock (white) with texture (white) and joint compound (white) / Office A120 in corner	ND	NF
* A-13	Sheetrock (white) with texture (white) and joint compound (white) / Hallway outside Office A121	2%C-TX 2%C-JC	NF
A-14	Sheetrock (white) with texture (white) and joint compound (white) / Cashier Lobby by entrance	ND	NF
* A-15	Sheetrock (white) with texture (white) and joint compound (white) / Storage closet outside Office 124	3%C-TX 3%C-JC	NF
* A-16	Sheetrock (white) with texture (white) and joint compound (white) / Women's Restroom near Cashier's office	3%C-TX 3%C-JC	NF
A-17	Cove base (black) and mastic (tan) / Women's Restroom near Cashier's office	ND	NF
A-18	Cove base (black) and mastic (tan) / Office A117 by entrance	ND	NF
A-19	Cove base (black) and mastic (tan) / Office A104 by entrance	ND	NF
A-20	12"x12" Floor tile (beige with white pattern) and mastic (yellow) / Electrical closet across from Reception area	ND	NF
A-21	Roof flashing (black) / South roof Southeast corner	ND	NF
A-22	Roof flashing (black) / South roof Southwest corner	ND	NF
A-23	Roof flashing (black) / South roof Northwest corner	ND	NF
A-24	Roof core (black) and insulation (brown) / South roof Southeast corner	ND	NF
A-25	Roof core (black) and insulation (brown) / South roof Southwest corner	ND	NF
A-26	Roof core (black) and insulation (brown) / South roof Northwest corner	ND	NF


SAMPLE NO.	LOCATION / DESCRIPTION	PERCENT ASBESTOS	F/NF
A-27	Mastic (black) / Air duct penetration South roof	ND	NF
A-28	Mastic (black) / Air duct penetration South roof	ND	NF
A-29	Mastic (black) / Air duct penetration South roof	ND	NF
A-30	Roof core (black) and insulation (brown) / North roof Northeast corner	ND	NF
A-31	Roof core (black) and insulation (brown) / North roof Northwest corner	ND	NF
A-32	Roof core (black) and insulation (brown) / North roof Southwest corner	ND	NF
A-33	Roof flashing (black) / North roof Northeast corner	ND	NF
A-34	Roof flashing (black) / North roof Northwest corner	ND	NF
A-35	Roof flashing (black) / North roof Southwest corner	ND	NF

F	Friable	С	Chrysotile	JC	Joint Compound	TSI	Thermal System Insulation
NF	Non-Friable	Μ	Mastic	W	Wrap	*	Positive for Asbestos
ND	None Detected	FT	Floor Tile	ТΧ	Texture	**	Positive Stop Method
NA	Not Analyzed	L	Linoleum	I	Insulation		

5.0 CONCLUSIONS AND RECOMMENDATIONS

This study was generally non-destructive in scope and may have not located all potentially hidden ACBM within the subject property. However, we have attempted to sample all obvious and accessible suspect materials within the scope of this study. Our survey **has** revealed the presence of ACM at the subject property. These materials appeared to be in a fair condition at the time of our inspection.

These materials should be monitored for any changes in their condition by the management. Any ACM that might be impacted during renovation and/or demolition activities must be addressed prior to start of such activities by a qualified and licensed environmental company. Please advise us in advance for any scheduled renovation activities and we would be glad to work with Kellogg, Brown, & Root, Inc. to address the ACM in a timely manner.





	Ronnie Morgan ERC Environmenta 10801 Hammerly B Suite 100 Houston, TX 77043	lvd	Customer ID: Customer PO: Received: EMSL Order:	ERC50 09/03/09 9:45 AM 150904913	
Fax: Project:	(713) 290-9441 0907202/9910 Cash Rd.	Phone: (713) 290-94 Building A	44 EMSL Proj: Analysis Date:	9/17/2009	

				Non-Asb	<u>bestos</u>	Asbestos
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре
A-01-Sheetrock 150904913-0001		White Fibrous Homogeneous	10%	Cellulose	90% Non-fibrous (other)	None Detected
A-01-Texture 150904913-0001A		White Non-Fibrous Heterogeneous			98% Non-fibrous (other)	2% Chrysotile
A-01-Joint Compound 150904913-0001B		White Non-Fibrous			98% Non-fibrous (other)	2% Chrysotile
A-02-Sheetrock 150904913-0002		Homogeneous White Fibrous Homogeneous	10%	Cellulose	90% Non-fibrous (other)	None Detected
A-02-Texture 150904913-0002A		White Non-Fibrous Heterogeneous			98% Non-fibrous (other)	2% Chrysotile
A-02-Joint Compound 150904913-0002B		White Non-Fibrous Homogeneous			98% Non-fibrous (other)	2% Chrysotile

Report Amended: 9/17/2009 3:56:38 PM Replaces the Inital Report . Reason Code: Client-Samples Added

Analyst(s)

Jenny Drapela (59) Michelle Leggett (17)

Watelle

Michelle Legget, Lab Manager or other approved signatory

Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. The limit of detection as stated in the method is 1%. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of EMSL Analytical, Inc. EMSL's liability is limited to the cost of analysis. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government.

Samples analyzed by EMSL Analytical, Inc. Houston 2501 Central Parkway, Suite C-17, Houston TX NVLAP Lab Code 102106-0, AZ 0925, CO AL-15355, LA 04126, TX 300159



	Ronnie Morgan ERC Environment 10801 Hammerly E Suite 100 Houston, TX 7704	Blvd	tants, Inc.	Customer ID: Customer PO: Received: EMSL Order:	ERC50 09/03/09 9:45 AM 150904913	
Fax: Project	(713) 290-9441 : 0907202/9910 Cash Rd	Phone: I . Building A	(713) 290-9444	EMSL Proj: Analysis Date:	9/17/2009	

				Non-Asb	<u>bestos</u>	Asbestos
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре
A-03-Sheetrock 150904913-0003		White Fibrous Homogeneous	10%	Cellulose	90% Non-fibrous (other)	None Detected
A-03-Texture 150904913-0003A		White Non-Fibrous Heterogeneous			98% Non-fibrous (other)	2% Chrysotile
A-03-Joint Compound 150904913-0003B		White Non-Fibrous Homogeneous			98% Non-fibrous (other)	2% Chrysotile
A-04-Sheetrock 150904913-0004		White Fibrous Homogeneous	10%	Cellulose	90% Non-fibrous (other)	None Detected
A-04-Texture 150904913-0004A		White Non-Fibrous Heterogeneous			98% Non-fibrous (other)	2% Chrysotile
A-04-Joint Compound 150904913-0004B		White Non-Fibrous Homogeneous			98% Non-fibrous (other)	2% Chrysotile

Report Amended: 9/17/2009 3:56:38 PM Replaces the Inital Report . Reason Code: Client-Samples Added

Analyst(s)

Jenny Drapela (59) Michelle Leggett (17)

Watelle

Michelle Legget, Lab Manager or other approved signatory



Attn:	Ronnie Morgan ERC Environment		tants, Inc.	Customer ID: Customer PO:	ERC50	
	10801 Hammerly I	biva		Received:	09/03/09 9:45 AM	
	Suite 100			EMSL Order:	150904913	
	Houston, TX 7704	3				
Fax:	(713) 290-9441	Phone:	(713) 290-9444	EMSL Proj:		
Project	t: 0907202/9910 Cash Ro	d. Buildina A		,	- /	
				Analysis Date:	9/17/2009	

				<u>Non-Asb</u>	<u>Asbestos</u> % Type	
Sample	Description	Appearance	% Fibrous			% Non-Fibrous
A-05-Sheetrock 150904913-0005		White Fibrous Homogeneous	10%	Cellulose	90% Non-fibrous (other)	None Detected
A-05-Texture 150904913-0005A		White Non-Fibrous Heterogeneous			98% Non-fibrous (other)	2% Chrysotile
A-05-Joint Compound 150904913-0005B		White Non-Fibrous Homogeneous			98% Non-fibrous (other)	2% Chrysotile
A-06-Cork Board 150904913-0006		Tan Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
A-06-Mastic 150904913-0006A		Brown Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
A-06-Ceiling Tile 150904913-0006B		White/Beige Fibrous Homogeneous	60%	Cellulose	40% Non-fibrous (other)	None Detected
A-07-Cork Board 150904913-0007		Tan Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected

Report Amended: 9/17/2009 3:56:38 PM Replaces the Inital Report . Reason Code: Client-Samples Added

Analyst(s)

Jenny Drapela (59) Michelle Leggett (17)

Watelle 215

Michelle Legget, Lab Manager or other approved signatory



	Ronnie Morgan ERC Environment 10801 Hammerly I Suite 100	Blvd	s, Inc.	Customer ID: Customer PO: Received: EMSL Order:	ERC50 09/03/09 9:45 AM 150904913	
	Houston, TX 7704	3				
Fax:	(713) 290-9441	Phone: (713)	290-9444	EMSL Proj:		
Project	: 0907202/9910 Cash Ro	I. Building A		Analysis Date:	9/17/2009	

				<u>Non-Ast</u>	<u>Asbestos</u> % Type	
Sample	Description	Appearance	% Fibrous			% Non-Fibrous
A-07-Mastic 150904913-0007A		Brown Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
A-07-Ceiling Tile 150904913-0007B		White/Beige Fibrous Homogeneous	60%	Cellulose	40% Non-fibrous (other)	None Detected
A-08-Cork Board 150904913-0008		Tan Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
A-08-Mastic 150904913-0008A		Brown Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
A-08-Ceiling Tile 150904913-0008B		White/Beige Fibrous Homogeneous	60%	Cellulose	40% Non-fibrous (other)	None Detected
A-09-Sheetrock 150904913-0009		White Fibrous Homogeneous	10%	Cellulose	90% Non-fibrous (other)	None Detected
A-09-Texture 150904913-0009A		White Non-Fibrous Heterogeneous			98% Non-fibrous (other)	2% Chrysotile

Report Amended: 9/17/2009 3:56:38 PM Replaces the Inital Report . Reason Code: Client-Samples Added

Analyst(s)

Jenny Drapela (59) Michelle Leggett (17)

Judelle W 218

Michelle Legget, Lab Manager or other approved signatory



Attn:	Ronnie Morgan ERC Environment		ants, Inc.	Customer ID: Customer PO:	ERC50	
	10801 Hammerly I	Biva		Received:	09/03/09 9:45 AM	
	Suite 100			EMSL Order:	150904913	
	Houston, TX 7704	3				
Fax:	(713) 290-9441	Phone:	(713) 290-9444	EMSL Proj:		
Project	t: 0907202/9910 Cash Ro	1 Building A		EMSL FIOJ.		
1 10,000		a. Building A		Analysis Date:	9/17/2009	

		Non-Asbestos				<u>Asbestos</u>
Sample	Description	Appearance	% Fibrous		% Non-Fibrous	% Туре
A-09-Joint Compound 150904913-0009B		White Non-Fibrous			98% Non-fibrous (other)	2% Chrysotile
150904913-0009B		Homogeneous				
A-10-Sheetrock 150904913-0010		White Fibrous Homogeneous	10%	Cellulose	90% Non-fibrous (other)	None Detected
A-10-Texture 150904913-0010A		White Non-Fibrous Homogeneous			100% Non-fibrous (other)	<1% Chrysotile
A-10-Joint Compound 150904913-0010B		White Non-Fibrous Homogeneous			98% Non-fibrous (other)	2% Chrysotile
A-11-Sheetrock 150904913-0011		White Fibrous Homogeneous	10%	Cellulose	90% Non-fibrous (other)	None Detected
A-11-Texture 150904913-0011A		White Non-Fibrous Heterogeneous			98% Non-fibrous (other)	2% Chrysotile

Report Amended: 9/17/2009 3:56:38 PM Replaces the Inital Report . Reason Code: Client-Samples Added

Analyst(s)

Jenny Drapela (59) Michelle Leggett (17)

Watelle

Michelle Legget, Lab Manager or other approved signatory



Attn:	Ronnie Morgan ERC Environment		ints, Inc.	Customer ID: Customer PO:	ERC50	
	10801 Hammerly I	Siva		Received:	09/03/09 9:45 AM	
	Suite 100			EMSL Order:	150904913	
	Houston, TX 7704	3				
Fax:	(713) 290-9441	Phone: (7	713) 290-9444	EMSL Proj:		
Projec	t: 0907202/9910 Cash Ro	I. Building A		Analysis Date:	9/17/2009	

			Non-Asbestos			<u>Asbestos</u>
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Type
A-11-Joint Compound 150904913-0011B						Not Submitted
A-12-Sheetrock 150904913-0012		White Fibrous Homogeneous	10%	Cellulose	90% Non-fibrous (other)	None Detected
A-12-Texture 150904913-0012A		White Non-Fibrous Heterogeneous			100% Non-fibrous (other)	None Detected
A-12-Joint Compound 150904913-0012B		White Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
A-13-Sheetrock 150904913-0013		White Fibrous Homogeneous	10%	Cellulose	90% Non-fibrous (other)	None Detected
A-13-Texture 150904913-0013A		White Non-Fibrous Heterogeneous			98% Non-fibrous (other)	2% Chrysotile

Report Amended: 9/17/2009 3:56:38 PM Replaces the Inital Report . Reason Code: Client-Samples Added

Analyst(s)

Jenny Drapela (59) Michelle Leggett (17)

Watelle

Michelle Legget, Lab Manager or other approved signatory



Attn:	Ronnie Morgan ERC Environment		ants, Inc.	Customer ID: Customer PO:	ERC50	
	10801 Hammerly I	Biva		Received:	09/03/09 9:45 AM	
	Suite 100			EMSL Order:	150904913	
	Houston, TX 7704	3				
Fax:	(713) 290-9441	Phone:	(713) 290-9444	EMSL Proj:		
Project	t: 0907202/9910 Cash Ro	1 Building A		EMSL FIOJ.		
1 10,000		a. Building A		Analysis Date:	9/17/2009	

			<u>bestos</u>	Asbestos		
Sample	Description	Appearance	% Fibrous		% Non-Fibrous	% Туре
A-13-Joint Compound 150904913-0013B		White Non-Fibrous			98% Non-fibrous (other)	2% Chrysotile
100004913-00132		Homogeneous				
A-14-Sheetrock 150904913-0014		White Fibrous Homogeneous	10%	Cellulose	90% Non-fibrous (other)	None Detected
A-14-Texture 150904913-0014A		White Non-Fibrous Heterogeneous			100% Non-fibrous (other)	None Detected
A-14-Joint Compound 150904913-0014B		White Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
A-15-Sheetrock 150904913-0015		White Fibrous Homogeneous	10%	Cellulose	90% Non-fibrous (other)	None Detected
A-15-Texture 150904913-0015A		White Non-Fibrous Heterogeneous			97% Non-fibrous (other)	3% Chrysotile

Report Amended: 9/17/2009 3:56:38 PM Replaces the Inital Report . Reason Code: Client-Samples Added

Analyst(s)

Jenny Drapela (59) Michelle Leggett (17)

Watelle

Michelle Legget, Lab Manager or other approved signatory

Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. The limit of detection as stated in the method is 1%. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of EMSL Analytical, Inc. EMSL's liability is limited to the cost of analysis. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government.

Samples analyzed by EMSL Analytical, Inc. Houston 2501 Central Parkway, Suite C-17, Houston TX NVLAP Lab Code 102106-0, AZ 0925, CO AL-15355, LA 04126, TX 300159



Attn:	Ronnie Morgan ERC Environmenta 10801 Hammerly E	al Consultants, Inc. Blvd	Customer ID: Customer PO: Received:	ERC50 09/03/09 9:45 AM
	Suite 100 Houston, TX 77043		EMSL Order:	150904913
Fax: Projec	(713) 290-9441 t: 0907202/9910 Cash Rd	Phone: (713) 290-9444 . Building A	EMSL Proj: Analysis Date:	9/17/2009

		Non-Asbestos				Asbestos	
Sample	Description	Appearance	% Fibrous		% Non-Fibrous	% Туре	
A-15-Joint Compound 150904913-0015B		White Non-Fibrous			97% Non-fibrous (other)	3% Chrysotile	
130304313-00135		Homogeneous					
A-16-Sheetrock 150904913-0016		White Fibrous Homogeneous	10%	Cellulose	90% Non-fibrous (other)	None Detected	
A-16-Texture 150904913-0016A		White Non-Fibrous Heterogeneous			97% Non-fibrous (other)	3% Chrysotile	
A-16-Joint Compound 150904913-0016B		White Non-Fibrous Homogeneous			97% Non-fibrous (other)	3% Chrysotile	
A-17-Cove Base 150904913-0017		Black Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected	
A-17-Mastic 150904913-0017A		Tan Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected	

Report Amended: 9/17/2009 3:56:38 PM Replaces the Inital Report . Reason Code: Client-Samples Added

Analyst(s)

Jenny Drapela (59) Michelle Leggett (17)

Watelle 295

Michelle Legget, Lab Manager or other approved signatory



	Ronnie Morgan ERC Environment	al Consultants, Inc.	Customer ID: Customer PO:	ERC50
	10801 Hammerly I	Blvd	Received:	09/03/09 9:45 AM
	Suite 100		EMSL Order:	150904913
	Houston, TX 7704	3		
Fax:	(713) 290-9441	Phone: (713) 290-9444	EMSL Proj:	
Project	: 0907202/9910 Cash Ro	d. Building A	Analysis Date:	9/17/2009

			Asbestos		
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Туре
A-18-Cove Base 150904913-0018		Black Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
A-18-Mastic 150904913-0018A		Tan Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
A-19-Cove Base 150904913-0019		Black Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
A-19-Mastic 150904913-0019A		Tan Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
A-20-Floor Tile 150904913-0020		White/Beige Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
A-20-Mastic 150904913-0020A		Yellow Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
A-21 150904913-0021		Black Fibrous Homogeneous	10% Synthetic	90% Non-fibrous (other)	None Detected

Report Amended: 9/17/2009 3:56:38 PM Replaces the Inital Report . Reason Code: Client-Samples Added

Analyst(s)

Jenny Drapela (59) Michelle Leggett (17)

Judelle W ×15

Michelle Legget, Lab Manager or other approved signatory



Attn:	Ronnie Morgan ERC Environmenta 10801 Hammerly B Suite 100 Houston, TX 77043	lvd	, Inc.	Customer ID: Customer PO: Received: EMSL Order:	ERC50 09/03/09 9:45 AM 150904913
Fax: Project	(713) 290-9441 0907202/9910 Cash Rd.		290-9444	EMSL Proj: Analysis Date:	9/17/2009

			<u>Asbestos</u>			
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре
A-22 150904913-0022		Black Fibrous Heterogeneous	10%	Synthetic	90% Non-fibrous (other)	None Detected
A-23 150904913-0023		Black Fibrous Heterogeneous	10%	Synthetic	90% Non-fibrous (other)	None Detected
A-24-Roof Core 150904913-0024		Black Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
A-24-Insulation 150904913-0024A		Brown Fibrous Homogeneous	80%	Cellulose	20% Non-fibrous (other)	None Detected
A-25-Roof Core 150904913-0025		Black Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
A-25-Insulation 150904913-0025A		Brown Fibrous Homogeneous	80%	Cellulose	20% Non-fibrous (other)	None Detected
A-26-Roof Core 150904913-0026		Black Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected

Report Amended: 9/17/2009 3:56:38 PM Replaces the Inital Report . Reason Code: Client-Samples Added

Analyst(s)

Jenny Drapela (59) Michelle Leggett (17)

Judelle W ×15

Michelle Legget, Lab Manager or other approved signatory



ER 103 Su	onnie Morgan C Environmental (801 Hammerly Blvo ite 100 ouston, TX 77043	•	Customer ID: Customer PO: Received: EMSL Order:	ERC50 09/03/09 9:45 AM 150904913
```	(713) 290-9441 0907202/9910 Cash Rd. Bu	Phone: (713) 290-9444 i <b>ilding A</b>	EMSL Proj: Analvsis Date:	9/17/2009

			<u>bestos</u>	Asbestos		
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре
A-26-Insulation 150904913-0026A		Brown Fibrous Homogeneous	80%	Cellulose	20% Non-fibrous (other)	None Detected
A-27 150904913-0027		Black Fibrous Homogeneous	20%	Cellulose	80% Non-fibrous (other)	None Detected
A-28 150904913-0028		Black Fibrous Homogeneous	20%	Cellulose	80% Non-fibrous (other)	None Detected
A-29 150904913-0029		Black Fibrous Homogeneous	20%	Cellulose	80% Non-fibrous (other)	None Detected
A-30-Roof Core 150904913-0030		Black Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
A-30-Insulation 150904913-0030A		Brown Fibrous Homogeneous	80%	Cellulose	20% Non-fibrous (other)	None Detected
A-31-Roof Core 150904913-0031		Black Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected

Report Amended: 9/17/2009 3:56:38 PM Replaces the Inital Report . Reason Code: Client-Samples Added

Analyst(s)

Jenny Drapela (59) Michelle Leggett (17)

Judelle W z15

Michelle Legget, Lab Manager or other approved signatory



Attn:	Ronnie Morgan ERC Environment		ts, Inc.	Customer ID: Customer PO:	ERC50	
	10801 Hammerly	Blvd		Received:	09/03/09 9:45 AM	
	Suite 100			EMSL Order:	150904913	
	Houston, TX 7704	3				
Fax:	(713) 290-9441	Phone: (713	3) 290-9444	EMSL Proj:		
Projec	t: 0907202/9910 Cash Rd. Building A			,	0/17/0000	
,		e		Analysis Date:	9/17/2009	

			<u>Non-Asbestos</u>			
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре
A-31-Insulation 150904913-0031A		Brown Fibrous Homogeneous	80%	Cellulose	20% Non-fibrous (other)	None Detected
A-32-Roof Core 150904913-0032		Black Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
A-32-Insulation 150904913-0032A		Brown Fibrous Homogeneous	80%	Cellulose	20% Non-fibrous (other)	None Detected
A-33 150904913-0033		Black Fibrous Homogeneous	10%	Synthetic	90% Non-fibrous (other)	None Detected
A-34 150904913-0034		Black Fibrous Homogeneous	10%	Synthetic	90% Non-fibrous (other)	None Detected
A-35 150904913-0035		Black Fibrous Homogeneous	10%	Synthetic	90% Non-fibrous (other)	None Detected

Report Amended: 9/17/2009 3:56:38 PM Replaces the Inital Report . Reason Code: Client-Samples Added

Analyst(s)

Jenny Drapela (59) Michelle Leggett (17)

Tribelle W 215


Michelle Legget, Lab Manager or other approved signatory


Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. The limit of detection as stated in the method is 1%. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of EMSL Analytical, Inc. EMSL's liability is limited to the cost of analysis. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government.

Samples analyzed by EMSL Analytical, Inc. Houston 2501 Central Parkway, Suite C-17, Houston TX NVLAP Lab Code 102106-0, AZ 0925, CO AL-15355, LA 04126, TX 300159

THIS IS THE LAST PAGE OF THE REPORT.

### APPENDIX B






### APPENDIX C















### APPENDIX D



# TEXAS DEPARTMENT OF STATE HEALTH SERVICES

## ERC ENVIRONMENTAL CONSULTANTS INC

is certified to perform as a

### Asbestos Consultant Agency

in the State of Texas within the purview of Texas Occupations Code, chapter 1954, so long as this license is not suspended or revoked and is renewed according to the rules adopted by the Texas Board of Health.

David . They

COMMISSIONER OF HEALTH DAVID LAKEY, M.D.

License Number: 100431

NON-TRANSFERABLE VOID IF ALTERED

(Void After Expiration Date)

Expiration Date: 2/20/2010

Control Number: 96097



DAVID L. LAKEY, M.D. COMMISSIONER

### **TEXAS DEPARTMENT OF STATE HEALTH SERVICES**

1100 West 49th Street • Austin, Texas 78756 P.O. Box 149347 • Austin, Texas 78714-9347 1-888-963-7111 • <u>www.dshs.state.tx.us</u> TTY: 1-800-735-2989

APRIL 21, 2009

KOMMY M AZARPOUR ENVIRONMENTAL RESOURCE CONSULTANTS 10801 HAMMERLY BOULEVARD #100 HOUSTON, TX 77043

This is to verify that the individual shown below holds a valid credential to practice as an ASBESTOS INDIVIDUAL CONSULTANT in the State of Texas.

NAME: KOMMY M AZARPOUR LICENSE TYPE: ASBESTOS INDIVIDUAL CONSULTANT LICENSE NUMBER: 105238 CONTROL NUMBER: 95758 EXPIRATION DATE: 4/27/2011

If you have any questions, please contact us by phone at 512-834-6600, by fax at 512/834-6614. We encourage you to visit our website at http://www.dshs.state.tx.us for frequently updated information, including rules, laws, publications and forms. You may also verify a credential through this website.

Environmental & Sanitation Licensing Group



### **TEXAS DEPARTMENT OF STATE HEALTH SERVICES**

DAVID L. LAKEY, M.D. COMMISSIONER 1100 West 49th Street • Austin, Texas 78756 P.O. Box 149347 • Austin, Texas 78714-9347 1-888-963-7111 • <u>www.dshs.state.tx.us</u> TTY: 1-800-735-2989

JULY 17, 2008

RONNIE J MORGAN 10801 HAMMERLY BLVD SUITE 100 HOUSTON, TX 77043

This is to verify that the individual shown below holds a valid credential to practice as an ASBESTOS INDIVIDUAL MANAGEMENT PLANNER in the State of Texas.

NAME: RONNIE J MORGAN LICENSE TYPE: ASBESTOS INDIVIDUAL MANAGEMENT PLANNER LICENSE NUMBER: 205644 CONTROL NUMBER: 95523 EXPIRATION DATE: 7/14/2010

If you have any questions, please contact us by phone at 512-834-6600, by fax at 512/834-6614. We encourage you to visit our website at http://www.dshs.state.tx.us for frequently updated information, including rules, laws, publications and forms. You may also verify a credential through this website.

Environmental & Sanitation Licensing Group

### APPENDIX E